

THE ANDHRA PRADESH STATE CO-OPERATIVE BANK Ltd.,

(A State Govt. Partnered Scheduled Bank)
HO: NTR Sahakara Bhavan, # 27-29-28, Governorpet, Vijayawada-520 002.
Unl: http://www.apcob.org Email-premises@apcob.org

Date: 22.05.2023

TENDER NOTICE

Interior works in APCOB Kanuru Branch

Sealed Quotations are invited from GST registered firms for undertaking interior works tabulated below in Kanuru Branch of The A.P. State Co-operative Bank Ltd., at Vijayawada.

Time Schedule:

Quotation calling date - 22.05.2023 Quotation closing date - 25.05.2023 up to 10:30 AM Quotation opening date - 25.05.2023 at 03:00 PM Contact Person - DGM (GAD)

Note:

 Valuation of work is subjected to actual measurements by Bank's consultant Civil Engineer.

2. The relevant Scope of Work is attached.

If your firm is interested in participation and having its Registered/Branch Office at Vijayawada with AP GST No., please submit your quotation (inclusive of all taxes) to :

M Shyama Sundara Rao
DY. GENERAL MANAGER (GAD)
THE A.P. STATE CO.OPERATIVE BANK LTD.,
HO: NTR Sahakara Bhavan, # 27-29-28, Governorpet, Vijayawada-520 002.
Phone: (0866) 2429044, 088, 7729996777

SI.	Descripti	Nos	M	easure	ments	Qty	Unit	Rate	Amou		
No.	THE RESIDENCE OF THE PARTY OF T		L	В	D				nt		
(A	Repairs to Interior work a	t APCOI	Kanu	ru Bran	ch/VIJ	ayawada					
1	PARTITIONS - Providing at										
	design with 2" x 2" Maranti/Sal wood section finished frame										
	work @ 2'0" c/c both ways screwed to the floor and ceiling with										
	M.S. Cleats and to be treated with anti termite oil .The										
		measurement will be taken upto the false ceiling visible height									
	in case of full height partition. The frame work will be cladded										
	with 6mm thk comm. ply bo										
	thk. laminate (color with vertical grain) as per design with										
	adhesive and 3" high laminate skirting to be fixed bottom side of the partition. Extra frame work to be fixed for fixing glass. In										
					-	glass. In					
	the glazed partition 10 mm										
	blusting/granular blasting to be provided duly fixed with .										
	wooden lipping 37mm x 19 mm all complete duly polished. The										
	work to be completed as per design approval of the archiect. (Existing Damaged partiions Reapirs)										
	BM Room Partition	1 1	2.50	7.00		17.50					
	BM Room Partition	1	1.50	7.00		10.50					
	Partition at Wash area	1	4.50	8.25	-	37.13					
	D/d Door area	-1	3.00	7.00	-	-21.00					
	Back office Table Partition	1	5.00	6.00	-	30.00					
						74.13					
2	Labour Charges for Removing of Old Full/Low Height Partitions										
	with Glass and refixing with alterations for Branch area including										
	cost of al required materials and tools and paints and all labour										
	charges for fininsed item of work										
	BM Room Partition	1	2.50	7.00	-	17.50					
	BM Room Partition	1	1.50	7.00	-	10.50					
	Partition at Wash area	1	4.50	8.25	-	37.13					
	D/d Door area	-1	3.00	7.00	-	-21.00					
	Back office Table Partition	1	5.00	6.00	-	30.00					
	Table	1	4.50	2.50	-	11.25					
						85.38					

SI.	Descriptio	Nos.	Me	asuren	ients	Qty	Unit	Pate I	1
3	INC CTOP			6			JIIIE	Rate	Amou
3	LHS- STORAGE - Providing a	nd fixin	g Full he	right ste	orage i	400mm			***
	The second of 13mm blood blood broaded with a decident								
	The drawers to be made as a state of the								
	Thorn and in the tront								
	Actorial Algini Paldez to be wi								
	Lugae out of build bikwood a								
	I allowed his ou dismer sliding								
	Tout of 19mm block board an								
	leasing on bowder coated tha								
	lest to be provided . 3" x1/2 wondon chiriting to be associated at a								
	possited as per matching tone all along the visible seems tones.								
	Laur on on the enamel bainted								
	the unit to be enamel painted in matching tone. All the exposed edeges of the boards/plywoods to be coverd with								
	wooden lippings/mould	linne		46.6	a make	- W			
	complete. The work to be completed as per approval and approval								
	Architect								
	at Cah counter	2	3.00	2.50	-	15.00			
	at Back office Table	1	3.25	2.50	-	8.13	-		
						23.13			
4	BACK OFFICE TABLE - Providing and fixing tables made out of								
	The second with vertical drain) as see dealer in the								
	The state of the s								
	I am and a second secon	15D (D	D PENNS	100 84 1		A			
	The second secon	amınatı	ed in the	frant .	Windows &				
	and and	Dottor	to be m	anda a	4 -6 0-				
	in a silver play in dray	out of 12mm comm. plyw and bottom to be made out of 6mm comm. ply and it should play in drawer sliding channels. The inside of the							
	drawer and the table to be duly paint. A leg rest to be provided out of							-	
	3"x2" this wooden section. A	shutter	r to he	made h	e prov	ided out of		1	
	board cladded with 1.0 mm la								
	be provided in each drawers								
	be provided in each drawers and shutters. On top of the Branch managers table 10mm thk glass to be placed duly edge polished. The								
	table should have key board to								
	mm laminate. The necessary								
	tables and provision for lights								
	table.	LO DE KI	ept ii ret	loued II	i the t	ront of the			
	OFFICER AND SECOND OFFICE								
	The state of the s	1	1.00		-6"}				
		1	1.00	1.00	-	1.00			
						1.00	Nos.		
5	Repairs- Key Board Charles	0-							
	Repaits- Key Board Channes Repairs with New Channels to be								
	provided everywhere with a provision of castors to be provided . 19mm comm. board & 12mm ply panel fix front side as per as per								
	I Sommit Dode of 15mm								
	design including the raised leve								
-									
	key Board Channes Repairs wit								
	Key Board Channes Repairs wit	2				1 200			
	key Board Channes Repairs wit		1.00	1.00	*	2.00	Nos.		

SI. No.	Descrip tion	Nos	Me	asure	ment	Qty	Unit	Rate	Amou
			5						nt
-			L	В	D				
6	Repaits- Key Board Channes Repairs with New Channels to be								
	provided everywhere with a								
	.19mm comm. board & 12m								
	per design including the rais	ed lev	vel & pe	rforation	ons.				
	Key Board Channes Repairs								
	The state of the s	2	1.00	1.0	1	2.00			
		_	1.00	0	-	2.00			
						2.00	Nos.		
7	Floor Springs: Supply and Fixing of Floor Springs Heavy duty								
	(Hardwin Make/ any ISI Approved) for Partiton Doors at Sections								
	including cutting of Floor and								
	fixing properly to the Door at	1 1							
	Main Entrance Floor Spring	1	-	-	-	1.00			
	,					1.00	Nos.		
8					1		1		
8	Removing of Old Damaged	Reed	ing and	Eiving	Now	Donding			
8	Removing of Old Damaged whre it will required proper	Beed ly and	ing and	Fixing	New	Beeding			
8	whre it will required proper	ly and	d includi	ina co	New st of E	Beeding Beedinga			
8	whre it will required proper and Fixing of Labour Charge	ly and s Etc.,	d includ , comple	ing co	New st of E	Beedinga			
8	whre it will required proper	ly and	d includi	ina co	New st of E	Beeding Beedinga			
8	whre it will required proper and Fixing of Labour Charge Beeding to Doors and	ly and s Etc.,	comple	ing coste te	New st of E	Beedinga			
8	whre it will required proper and Fixing of Labour Charge Beeding to Doors and	ly and s Etc.,	comple	ing coste te	New st of E	100.00 100.00	Rft		
8	whre it will required proper and Fixing of Labour Charge Beeding to Doors and	ly and s Etc.,	comple	ing coste te	New st of E	100.00 100.00 Tot	Rft al in R	s.	
8	whre it will required proper and Fixing of Labour Charge Beeding to Doors and	ly and s Etc.,	comple	ing coste te	New st of E	100.00 100.00 Tot	Rft tal in R	s.	